

-Replacement Sheet-

1/12

100




FIG. 1

-Replacement Sheet-






FIG. 2

-Replacement Sheet-





-Replacement Sheet-




FIG. 5A

-Replacement Sheet-






FIG. 5B

-Replacement Sheet-



-Replacement Sheet-

7/12



TimeOUt1, Programmable parameter ACK_WAT_SIZE:
6, 12, 18, 24, 36, 48, 72, 90 US
TimeOut2, fixed size: 37.125 us which is the maximum length of an acknowledge packet (24 preamble + sfd + 20 byte ack_packet)

FIG. 5D

-Replacement Sheet-




FIG. 6A.

-Replacement Sheet-






FIG. 6B

-Replacement Sheet-





FIG. 6C

-Replacement Sheet-



p. 17 of 20

TITLE:FREQUENCY OFFSET DIFFERENTIAL PULSE POSITION MODULATION
INVENTOR(S): John B. Langley
ATTORNEY DOCKET NO.: 012.P6002

-Replacement Sheet-

12/12

For preamble the following sequence is received: 00, 11, 01, 10 and the state machine tries to lock on this sequence. For SFD the sequence is 00, 00, 01, 11




FIG. 6E

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
☐ GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
OTHER.

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.